Good/Bad/Ug

Mike Riley IPM Associates, Inc. 2400 Chamberlain Drive Plano, Texas 75023 www.ipmassociates.com

Forget the Good

- The Bad:
 - Lubricants
 - Greases
 - UHMW Warps
 - Rubber Hoses
 - Sprinkler Heads
 - Epoxy Paints
 - Mesh Screens in Sifters
 - Floor Coatings



Lubricants

Greases

UHMW Materials

• Rubber Hoses






Epoxy Paints





Epoxy Paints

Epoxy Paints



 Mesh Screens in Sifters



Floor Coatings





Photo 15: Fluid filled bilister at location S-3.

Floor Coatings




- The Ugly:
 - Floor Coatings Buckling
 - Control Panel Switch Gear Melt Down
 - Computer PLC Melt Down
 - Fire Control Systems Compromised
 - Pressurized Containers Explode

- The Ugly:
 - Ingredient Degradation
 - Low-Temp Wire Coating Melted
 - YOU ARE OUT OF CONTROL IT'S CONTROLLING YOU!

•THE UGLY

 Floor Coatings Buckling





hoto 11: Coating removed at S-2.





Control Panel
Switch Gear
Meltdown



Do Not Overlook PLC Cards

 Could be Major Meltdown







 Fire Control Systems Compromised
Consider 19 Sprinklers Open at Same Time

Pressurized
Containers
Explode

- Ingredient Degradation
 - IBC Storage?



- Low-Temp Wire Coating Meltdown
- Hydraulic Hoses

?????

If you are considering Heat... Inspections/Needs Analysis Consulting WE CAN HELP IPM ASSOCIATES, INC www.ipmassociates.com

